

RELEASE NOTES

The EFI™ Fiery® proServer and Fiery XF 6.5.1 update is recommended for all version 6.5 users. No new license is needed for customers who have a 6.5 license installed.

Fiery XF version 6.5.1 resolves the following issues:

Nesting

- Cut contour extraction results in an empty cut file
- Wrong cut mark placement when using bleed, resulting also in job preview issues
- Shifted Zünd cut paths for certain job margin combinations
- Missing cut path in the Zünd file when having copies within a nest

Profiling

- There was a risk of unwanted reversals, which is resolved by using the updated printer presets
- Long profiling calculation times

Color

- Oversaturated printouts using Black Point Compensation with v4 ICC profiles

Printer

- No printer connection to Canon imagePROGRAF iPF Pro series on Mac
- Unprintable multipage files on Epson SC-P5000

Others

- Missing license information on Mac
- CRPC6-Idealliance ISO 12647-7 CW 2013 GRACoL2013_CRPC6 Ref.it8 characterization data not compatible with the Idealliance ISO 12647-7 Control Wedge 2013 (EPSON ILS30EP 2rows)
- Job preview issues for EFI Matan and Quantum printers
- Extended startup time for RGB Profiler Connector on Windows 10
- Outdated support contact information for India

Availability

- Fiery XF 6.5.1 is available via the Online Updater for all configurations of Fiery proServer and Fiery XF version 6.5. Alternatively, the version 6.5.1 update can be downloaded from the EFI downloads area <http://www.efi.com/products/inkjet-printing-and-proofing/fiery-for-inkjet/fiery-xf/download/>
- No new license is needed for customers who have a 6.5 license installed
- For customers who have not upgraded to version 6.5 yet, detailed instructions on how to upgrade and a complete list of new features, enhancements and a list of new supported printers are available in the [6.5 Release Notes](#)