KNOWN LIMITATIONS

Below are the known limitations to be aware of for EFI™ Fiery® proServer and Fiery XF 6.5:

Known Limitations

- IMPORTANT note for VUTEk 3r and 5r, Quantum 3 and 5, QuantumFlex 3 and 5:
  - Print mode names have been updated on the above printer platforms.
    - After upgrading to 6.5, your existing calibrations and profiles will remain working as before; but if you create a new calibration, the new names will be used automatically.
    - In order to process jobs with these new calibrations, you will have to update the printer software of the above platforms to "FE SW 11.0.12" or higher.
  - For additional support please contact: Matan-Service@efi.com
- IMPORTANT note for Quantum LXr 3 and 5:
  - Support for these printer models have been discontinued with version 6.5. The Quantum 3 and 5 printer drivers can be used instead. The EPLs remain compatible.
- The Reggiani folder path can only be configured from the Fiery XF Client that is running on the Fiery proServer station, and not while using a remote Fiery XF Client.
- Pre-linearization of fluorescent inks for EFI soft signage and textile printers is not included yet. The Color Tools provide options to pre-limit fluorescent inks with the pre-ink limit settings in the base linearization, or visual correction curves for spot colors (vcc), in the Visual Correction tool. Another option is to use the gradation curve functionality in the Color Editor tool.

For more information, contact your local Fiery proServer and Fiery XF dealer, or visit www.efi.com/products/inkjet-printing-and-proofing/fiery-for-inkjet.
EFI's portfolio of integrated solutions increase productivity and improve your bottom line.
Find out more at www.efi.com.