

RELEASE NOTES

The Fiery XF and the Software Maintenance and Support Agreement (SMSA) or your EFI Enhanced Service Program (ESP) provide an ongoing stream of features, improvements, fixes and latest print drivers. EFI is pleased to announce Fiery XF Version 6.0.2. The latest release will be available free of charge to everyone covered under the SMSA or ESP (with Fiery proServer included). The improvements included are:

Bug Fixes

- Fixed an issue that could lead to white stripes when large jobs were processed with FAST RIP
- Fixed an issue that would prevent plate compensation and visual correction curves to work for spot colors when FAST RIP is used
- Fixed a banding issue that occurred for some jobs that were processed with FAST RIP and Dynamic Smoothing
- Fixed distorted text that occur when jobs were processed with FAST RIP and the Adobe PDF Print Engine
- Fixed a stochastic screening (SE2) issue for EFI VUTEk printers that influenced the quality of fine contours and fonts
- Fixed printer driver issues for the HP Z5200 HT, Canon iPF 760 and 765, Canon iPF 6460 (measurement error) and the Epson SC-T5250
- Fixed potentially missing copies in nesting and step & repeat when APPE is used

For more information contact your local Fiery XF dealer or go to www.efi.com/fieryxf. EFI's portfolio of integrated solutions increases productivity and improves your bottom line. Find out more at www.efi.com.