



Customer Release Notes

Fiery XF, version 8.0.1

Fiery® is pleased to announce the release of Fiery XF 8.0.1. This latest Fiery software release is a server update for Fiery proServer and Fiery XF 8.0, which updates the Fiery XF server from 8.0 to 8.0.1.

New printer drivers

- Canon
 - imagePROGRAF GP-526S (Printer Option Group 4)
 - imagePROGRAF GP-546S (Printer Option Group 4)
 - imagePROGRAF GP-566S (Printer Option Group 4)
 - imagePROGRAF GP-2600S (Printer Option Group 4)
 - imagePROGRAF GP-4600S (Printer Option Group 4)
 - imagePROGRAF GP-6600S (Printer Option Group 4)
 - imagePROGRAF PRO-526 (Printer Option Group 4)
 - imagePROGRAF PRO-546 (Printer Option Group 4)
 - imagePROGRAF PRO-566 (Printer Option Group 4)
 - imagePROGRAF PRO-2600 (Printer Option Group 4)
 - imagePROGRAF PRO-4600 (Printer Option Group 4)
 - imagePROGRAF PRO-6600 (Printer Option Group 4)
- Dlican
 - BYHX-G6 (Printer Option Group 7)
 - KONICA-1024i (Printer Option Group 7)
- EPSON
 - SureColor SC-P700 (Printer Option Group 3)
 - SureColor SC-P900 (Printer Option Group 3)
 - SureColor SC-F6400 (Printer Option Group 4)



- SureColor SC-F6400H (Printer Option Group 4)
 - Support for CMYKcm and CMYKOV
- SureColor SC-P11000D (Printer Option Group 6)
- Mutoh
 - ValueJet 628MP (Printer Option Group 6)
- Roland DG
 - DGXPRESS ER-641 (Printer Option Group 6)
 - DGXPRESS ER-642 (Printer Option Group 6)
 - SF-200 (Printer Option Group 6)
 - VersaSTUDIO BN2-20 (Printer Option Group 4)
 - VersaSTUDIO BN2-20A (Printer Option Group 4)
 - VersaSTUDIO BY-20 (Printer Option Group 4)
- Plus support of 1,000+ additional printers that are available on request (contact LFsales@fiery.com), increasing the overall number of supported printer brands to 308 and the number of supported models to over 2,450.

Updated printer drivers

- Canon
 - Colorado M-Series
 - Multilayer printing up to 5 layers (CMYK-W-K-W-CMYK. Back side needs to use same image as on the front side (automatically mirrored))
- EFI
 - Reggiani all models
 - Added "IRIS Plus" ink support
 - VUTEk FabriVU/FabriVUi and FabriVU+/FabriVUi+
 - Added "ColorMax AQ" ink support
 - VUTEk F-Q3r/F-Q5r [FAST DRIVE]
 - Printer drivers to run VUTEk Q3r/Q5r models with FastClear option (only offered Clear option today)
 - Added as separate printer drivers next to the VUTEk Q3r/Q5r drivers (required to use if the regular Clear Option is installed, which was prior to the availability of the FastClear option)

- VUTEk Q3r/Q5r [FAST DRIVE]
 - Updated print modes
 - Removed print modes (and moved them to VUTEk F-Q3r/F-Q5r [FAST DRIVE]):
 - 4C-Coat_F-Gloss-Q
 - 4C-Coat_F-Matte-Q
 - 4C-CWC-B-Coat_F-Gloss-Q
 - 4C-CWC-B-Coat_F-Gloss-C1-Q
 - 4C-CWC-B-Coat_F-Gloss-C2-Q
 - 4C-WBWWC-Coat_F-Gloss-C1-Q
 - 4C-WBWWC-Coat_F-Gloss-C2-Q
 - W-Coat_F-Gloss-Q
 - W-Coat_F-Matte-Q
 - White-Under-Coat_F-Matte-Q
 - White-Under-Coat_F-Gloss-Q
 - Added print modes:
 - 4C-WWU-Coat-Gloss-Q
 - 4C-11Pass-Q

Cutting enhancements

- Support for material thickness added for materials loaded via Fiery Cutter Material Database Connector connecting to Zund ZCC Server and Eurosystem OptiScout 8 driven cutters
- Option added to keep cut files when deleting a job in Fiery Command WorkStation
 - For all cutters supported through the Cut Marks Option
- Option added to use cut image in bleed settings now for Summa GoProduce driven L-Series and F-Series cutters
- Support of cut marks placement by numbers now also for all Zund 3-Series models (D3, G3, L3, S3)

Security enhancements

- Transport Layer Security (TLS) 1.3 compatibility for Fiery Profile Online Updater
 - For compliance with NIST SP 800-52 for TLS implementation

Fixed issues

Fiery XF 8.0.1 server related fixes

- Fiery XF server-related fixes:
 - Fixed a problem with a nesting job with multiple jobs erroring out.
- Printer driver-related fixes:
 - Fixed a problem with Roland VersaUV LEJ-640 printer driver not saving the heater settings properly.
 - Fixed a problem with Canon imagePROGRAF iPF64x0/94x0 printer driver not being able to measure any chart using the internal spectrophotometer.
 - Fixed a problem with Canon imagePROGRAF iPF64x0/94x0 printer driver using LOP instead of RAW port protocol.
- FAST DRIVE-related fixes:
 - Fixed a problem with corrupted output using EFI VUTEk Q5r+ [FAST DRIVE] and EFI VUTEk 32r+ [FAST DRIVE].
- Nesting-related fixes:
 - Fixed a problem with orientation marks overlapping camera cut marks.

Availability

- The Fiery XF server 8.0.1 update is available as an online update through Fiery Server Control for all configurations of Fiery proServer and Fiery XF version 8.0.
- Alternatively, the Fiery XF server 8.0.1 update can be downloaded from the [Fiery Download Center](#).

Additional notes

- Fiery proServer and Fiery XF solutions are made from multiple software applications. A server application (Fiery XF server), a client application (Fiery Command WorkStation), plus color applications (Color Profiler Option and Color Verifier Option included within Fiery Color Profiler Suite).
- The following overview informs you about the Fiery XF server, Fiery Command WorkStation, and Fiery Color Profiler Suite versions required for the full support of features with Fiery XF 8.0.1:

	Fiery XF server	Fiery Command WorkStation Package	Fiery Color Profiler Suite
Fiery XF 8.0.1	8.0.1	7.0.0.490 or later	5.6.1.06 or later

	Fiery XF server	Fiery Command WorkStation Package	Fiery Color Profiler Suite
Supported Operating Systems	Microsoft Windows 10 (64-bit) Microsoft Windows 11 Microsoft Windows Server 2016 (64-bit) Microsoft Windows Server 2019 Microsoft Windows Server 2022	Microsoft Windows 10 (64-bit) Microsoft Windows 11 Microsoft Windows Server 2016 (64-bit) Microsoft Windows Server 2019 Microsoft Windows Server 2022 macOS 10.15 macOS 11 macOS 12 macOS 13 macOS 14	Microsoft Windows 10 (64-bit) Microsoft Windows 11 Microsoft Windows Server 2022 macOS 10.15 macOS 11 macOS 12 macOS 13 macOS 14

- The latest Fiery Command WorkStation and Fiery Color Profiler Suite versions are available through the Fiery Software Manager or the [Fiery Download Center](#) in the Application Software and Tools section.

Software Maintenance & Support Agreement (SMSA)

Fiery Software Maintenance & Support Agreements (SMSA) for Fiery proServer and Fiery XF provide an ongoing stream of features, improvements, fixes, and the latest printer and cutter drivers. Fiery XF 8.0.1 is available at no additional charge for all customers with their Fiery software covered under this agreement.

For more information, please contact your local Fiery XF dealer or visit <https://fiery.com/XF>.

Fiery's portfolio of integrated solutions increases productivity and improves your bottom line. Find out more at www.fierey.com.